MC2W3 C / MC2R3 C

megacon

The products MC2W3 A/B, and MC2R3 A/B Transducers have been superseded by MC2WC/D and MC2R3C/D respectively. The connection diagram is changed as shown.



The connection diagram below now applies.



NOTE:

1. To ensure correct power measurement, the inputs must be connected to the instrument terminals as shown below.

2. The use of screened cable is recommended for all signal lines.

1198 / A	DRAWN :	CHECKED :